

Hulamin Production – PPE requirements

The following minimum PPE is required to access the production areas with Hulamin.

Remelt Production Department:

Overall	Hulamin Remelt Issued Overall
Safety Shoes	Safety shoes with no laces
Socks	Flame-retardant socks
Hard Hat	Grey
Safety Glasses	SABS approved safety glasses
Ear Protection	SABS approved ear plug or ear muffs

All other production Departments:

Overall	Acid Resistant Overall
Safety Shoes	Safety shoes
Hard Hat	Blue (Hulamin Employees) Yellow (Contractors) White (Visitors)
Safety Glasses	SABS approved safety glasses
Ear Protection	SABS approved ear plug or ear muffs

Any other PPE requirement as determined by my scope of work planned for the specific area ie. Hot works/Civil/Confined Space/Working at heights will be mandatory.